

Minjar

Plant Refurbishment



Project

Refurbishment of plant from ROM to Gold Room inclusive of commissioning

Location

North Western Goldfields, WA

Client

Minjar Gold

Commencement Date

February 2012

Practical Completion

August 2013

Description

Plant-wide refurbishment and maintenance together with pump rebuilds, bearing changes, drive unit alignment checks and external gearing mesh. Other works involved upgrades including dust suppression and level control systems as well as replacement of chute platework, structural steel work, rectification of maintenance issues and installation of equipment. Design, fabrication and replacement of stacker conveyor trestle.

Refurbishment of the primary jaw crusher including machining of mechanical parts. Maintenance of the complete crushing circuit.

In addition, Como conducted an audit of the plant guarding and installed new guarding where lacking.

Project Manager

Martin Smith

Referee

Barend Knoetze (Mill Manager–Minjar)

Mob: 0448 774 166

Don Russell (General Manager–Minjar)

Mob: 0448 972 282

