

# Granny Smith Mine

## Crusher & Plant Maintenance, State Wide Dangerous Goods Assessment



### Project

Crushing Circuit and Plant Maintenance  
Site wide Dangerous Goods Assessment

### Location

Granny Smith Mine, Laverton WA

### Client

Barrick Gold

### Commencement Date

February 2012

### Practical Completion

Ongoing



### Description

Replacement of the Kemco crusher and maintenance of the complete crushing circuit, as well as maintenance of the Jaques primary crusher located on a parallel circuit.

Plant-wide maintenance and minor upgrades including replacement of chute platework, rectification of maintenance issues and installation of equipment purchased by Barrick for upgrading the plant.

In addition, Barrick conducted an audit of the dangerous goods on site and determined deficiencies that needed to bring the site into full compliance with the Australian Standards, WA DG Regulations and best-practice for Australian mine sites. Martin Smith engaged as a Dangerous Goods Consultant to drive this project to bring the site into full compliance.

### Project Manager

Martin Smith

### Referee

Wayne Gaiter (Operations Manager – Granny Smith)

Mob: 0427 479 592